

BOMBARDIER

AEROSPACE

Bombardier Inc.
400, Côte-Vertu West
Dorval, Québec H4S 1Y9
www.bombardier.com

TEL 514-855-5000
FAX 514-855-7401

April 1st, 2013

SPX Precision Components
70 Raynor Avenue
Ronkonkoma, NY
USA 11779

SAP Suppliers no: 131981
SAP Notification no: 1000047438

Attention: Michael Yannetti, Director of Quality
Subject: Approval letter

Dear Mr. Yannetti,

Bombardier Aerospace is pleased to inform you that SPX Precision Components located at 70 Raynor Avenue, Ronkonkoma, NY USA 11779 is now APPROVED to BAPS 168-013.

This approval is issued on the condition that your company continues to comply with QD 4.6-40: Bombardier Aerospace Requirements for Suppliers and maintain acceptable product delivery performances. Copy of the document can be found on the Bombardier Internet site at <http://www.bombardier.com/>, →“Aerospace”, →“Suppliers”, →“Current Suppliers”, →“Quality Assurance”, →“Documentation”.

Bombardier Aerospace Quality may elect to audit your facility at any time during or prior to any contract in order to:

- Assure continuing compliance with contractual and quality requirements.
- Investigate any quality problems and assure that effective corrective action measures are implemented.
- Evaluate the effect of any change in facility, process, equipment, or management.

Your approval status will be periodically reviewed and / or revised based on supplier performance. It is Bombardier Aerospace's policy to purchase only from approved suppliers who consistently meet our standards of quality and reliability. We look forward to a lasting relationship driven by a desire for continuous quality improvement.

Sincerely yours,



Raphaël Desjardins
Analyst, Quality assurance and supplier quality management
514-855-5001 x.59137
raphael.desjardins@aero.bombardier.com

cc: Don Busocker, Triumph Quality Manager
Nadia Costantino
Supplier file